

## SERVICE + MAINTENANCE

### Some information

#### Temperature Sensor (NTC)

##### Table of resistance

*Temperature °C*    *Resistance kOhm*

0	27.7
5	22.29
10	18.07
15	14.74
20	12.11
25	10.00

#### Measuring Point:

*Electronics*

loosen contact X108

Cable white / brown

